Г	ACTION	1	FOUR /FUNCTION LOCA		CDEW INDICATION	Г	NOTES
-	ACTION		EQUIP/FUNCTION LOST		CREW INDICATION	}	NOTES
1 F	PCS Node 1: TCS NODE1:TCS 'NODE1'		RPCM N1RS2 A (Type V)  Node1 Shell Htrs String B		Caution Messages:  Advisory Messages:  RPCM N1RS2_A Loss of	; ;	String B of the Node 1 and PMA 1 Shell Heaters are nominally
	sel Node 1 Htr [X] A [X] = 1 2 3 4 5 6 7 8 9  cmd Ena Opr  Execute				Comm - NOD1  Telemetry: PCS Node 1: EPS  Node1: EPS		primary.  2 Since the internal Early Comm equipment is lost, the entire Early Comm system is lost.
_	H Repeat				RPCM N1RS2 A - not Active		Power to the Port and Stbd antenna is
	Node 1: EPS: RPCM N1RS1 RPCM NIRS1 C	2	CBM N1 Stbd Pri 3 (Early		Active	    -	removed.  3 These CBMs are not planned to be used on 3A.
	sel RPC [X], [X] = 5 12  cmd Open Execute		Comm CTP) CBM N1 Stbd Pri 4 (Early Comm RFPDB)				
	Repeat						
	On MCC Go: Go to RPCM REMOVE AND REPLACE, all (SODF: OSO).						